
CITY OF BALTIMORE WET W SMOKE AND DYED W	Page 1 of 4	
Sewershed: JONES FALLS	Company: REI/DRAYCO	Date: 07/03/08
Test to be Performed: SMOKE	Ground Condition: DRY	Supervisor: ER
Manhole ID: S33QQ_040MH	Test ID: 0994-359	Notifications Made:_X (Residents, Fire, 311)

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM					Page 2 of 4				
Sewershed: JONES FALLS			Company: REI/DRAYCO			Date: 07/03/2008			
	be Performed:) vod Motori		Ground Condition:				Supervisor:E.R	
Smoke:X Dyed Water:		Dry: _X Damp: Wet:							
Manhole ID: S33QQ_040MH		Test ID: 0994-359			Notifications Made:X (Residents, Fire, 311)				
Field Sketch: (Show all Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)									
Defect	,	, ,		Source	,		Drainage		,
No.		Address		Туре	Location	Sector	Area	Severity	Photo Number
1	2500 MARYLA	ND AVE.		03	01	02	1	03	359_OB01-01
2	2508 MARYLA	ND AVE.		03	12	01	1	02	359_OB02-01
				OBSERV	ATION	CODES			
	Source Type	Location	Sector	Severity		Source Type	Location		
01	Main Sewer	Paved Concrete	Public	No Smoke	10	MH Frame S	Non-Paved		
	Service Line	Paved Asphalt	Private	Trace		Storm Drain			
	Cleanout	Paved Other		Moderate	12	Catch Basin/			
	Downspout	Driveway		Major		Storm Manh			
	Area Drain	Sidewalk				Storm Ditch	Other		
	Driveway Drain	Curb				Excavation			
	Stairwell Drain	Yard- Front				Other			
08	Foundation Drain	Yard-Back							
09	Building Interior	Yard- Side							

PAGE 3 OF 4

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY JONES FALLS SEWERSHED

BALTIMORE CITY PROJECT 994 REI/DRAYCO

Unique Test ID: 359	Date: 07/03/2008	Basin: JF-19
Defect No: OB01	Supervisor: E.R.	Dye Test Recommended: N
House No: 2500	Street Name: MARYLAND	Street Type: AVE.
Source Type: 03	Location: 01	Severity: 03
Sector: 02	Drainage Area: 1	

Comments: CLEAN OUT - AT GRADE - MISSING CAP

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 0994-359_OB01-01.jpg

PAGE 4 OF 4

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY JONES FALLS SEWERSHED

BALTIMORE CITY PROJECT 994 REI/DRAYCO

Unique Test ID: 359	Date: 07/03/2008	Basin: JF-19
Defect No: OB02	Supervisor: E.R.	Dye Test Recommended: N
House No: 2508	Street Name: MARYLAND	Street Type: AVE.
Source Type: 03	Location: 12	Severity: 02
Sector: 01	Drainage Area: 1	

Comments: CLEAN OUT - AT GRADE - BROKEN CAP

SMOKE TEST PHOTOGRAPHS



Photograph No: OB02-01 Filename: 0994-359_OB02-01.jpg